

VEHICLE INSPECTION REPORT

BV67GSU

Volkswagen Crafter CR35 2.0 TDI BMT 109PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/09/2017

VIN WV1ZZZ2EZG6062920

CAP Below £2,300.00

Year 2017

Body Style Panel Van MWB

Gearbox MANUAL

Mileage 142,316 Miles Not Warranted

MOT Due 01/10/2025

Gears 6

Fuel Type Diesel

CAP Clean £3,550.00

Colour WHITE

CAP Average £3,000.00

SIDE LOAD DOOR, E/ MIRRORS, TOW BAR, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Roof
Chipped
Multiple Chips



3: Bumper Front
Hole
UpTo 25mm



4: Wing nsf
Dented
Over 30mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Over 30mm



8: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Sill ns
Dented
With Paint Damage



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



14: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



15: Door nsr
Dented
Over 30mm




16: Door osr
Dented
Over 30mm



17: Qtr Panel osr
Rusted
Over 5mm



18: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Qtr Panel osr
Dented
Over 30mm



21: Qtr Panel osr
Chipped
Multiple Chips



22: Qtr Panel osr
Dented
Over 30mm



23: B Post os
Dented
Over 30mm



24: Door osf
Chipped
Multiple Chips



25: Screen Front
Chipped
Over 10mm



26: Seat Base Cover osf
Torn
Over 3mm



27: Seat Base Cover nsf
Burn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		