

VEHICLE INSPECTION REPORT

RV70DEU

Iveco Eurocargo 75-160


Inspection		Vehicle				
Serious Damage?	No	VAT Plus VAT				
		V5	Present			
Details						
Reg. date	22/10/2020	Body Style	Box Van		Gearbox	AUTOMATIC
Year	2020	MOT Due	Expired		Axle Combi	4x2
Mileage	55,931 Km Warranted	CAP Clean	£9,700.00		Rear Suspension	Steel
Fuel Type	Diesel	CAP Average	£9,250.00		Rear Doors	Roller
Colour	WHITE	CAP Below	£8,125.00		Tail Lift	Column
VIN	ZCFA875B702700742	Cab Type	DAY CAB			
Tyres						
NSF	NSI1	NSI2		NSI3		NSI4
OSF	OSI1	OSI2		OSI3		OSI4
Spare	NSO1	NSO2		NSO3		NSO4
	OSO1	OSO2		OSO3		OSO4

Photos

















Condition Check



Damage Photos



1: Moulding nsf Wing Scratched (Painted) Over 25mm Thru Paint



2: Door nsf Scratched Over 25mm Thru Paint



3: General Exterior Soiled Light



4: General Exterior Soiled Light



5: Bumper Rear Rusted Over 5mm

Interior

Carpet Condition Seat Condition	OK OK		Upholstery Condition Odour	OK -	
Engine Runs		OK	Gearbox 1st and Reverse	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	tic	OK
Parking Brake		OK	Gearbox Static Gear Sele	ection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminat	ed	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	minated	OK