

1. Vehicle Identification

- **Vehicle Type:** Semi-trailer
- **Make:** KÖGEL
- **Model:** SN 24 Cargo 35.0t
- **Version:** CO24P90/1110/13.95
- **VIN:** WK0S0002400284871
- **Registration Number:** WZ548FC
- **Info-Ekspert Number:** 175-00044
- **Year of Manufacture:** 2022
- **First Registration Date:** August 25, 2022
- **Technical Inspection Expiry Date:** July 24, 2025
- **Trailer Body Type:** Box trailer with curtain side tarpaulin
- **Permissible Gross Weight / Kerb Weight / Payload:** 35,000 kg / 6,260 kg / 28,740 kg
- **Axle Suspension / Wheelbase:** Air suspension / 1,310 mm
- **Paint Color:** Grey

2. Standard Equipment List

1. Edscha sliding roof
2. High double-wing portal rear doors (2680 mm) with 2 sets of locking bars
3. Pneumatic parking brake with spring actuator
4. Stanchions/Pillars: 3 pairs with 5 slat pockets each
5. Spare wheel basket for 2 wheels
6. Aluminum slats: 3 sets
7. Side tarpaulin: $\$900 \text{ g/m}^2$
8. SAF maintenance-free axles
9. Side underrun protection guards
10. Lifiable 1st axle
11. Waterproof plywood floor ($\$30 \text{ mm}$) thick, load capacity $\$7,200 \text{ kg}/\text{axle}$
12. Toolbox
13. $\$2"$ Kingpin
14. Roll Stability Support System (RSS)
15. Electronic Braking System (EBS)
16. Brake system with Automatic Load-Sensing Valve (ALB)

3. Tire Specifications

Tire Specification: CONTINENTAL 385/65 R22.5 164K HS 3+ HYBRID 20PR
(All Wheels)

- **Front Left:** 7.8 mm tread remaining
- **Front Right:** 6.3 mm tread remaining
- **2nd Axle Left:** 14.2 mm tread remaining
- **2nd Axle Right:** 14.0 mm tread remaining
- **3rd Axle Left:** 7.3 mm tread remaining
- **3rd Axle Right:** 8.3 mm tread remaining

4. Vehicle History & Legal Status Notes

- **Registration Certificate:** Lost under unknown circumstances according to information from the client.
- **Database Check (historiapojazdu.gov.pl):**
 - **17.04.2025:** Vehicle theft reported.
 - **24.06.2026:** Vehicle recovered / search closed.
- **VIN Verification:** VIN stamped on the frame and nameplate matches the CEPIK database.

5. Technical Condition & Visual Defects

- **Drive Test:** Not performed because the vehicle has no self-propulsion (unpowered trailer). There is a risk of detecting further defects during a road test.
- **Observed Defects & Deviations from Normal Condition:**
 - **Tarpaulin:** Scratches, torn material, and visible traces of repair.
 - **Front Left Corner:** Scratches.
 - **Front Right Corner:** Scratches.
 - **Rear Rubber Buffers / Bumpers:** Deformed.
 - **Rear Doors:** Dents.
 - **Right Side Underrun Guard:** Foci of corrosion.